



Welding



Automatic machine by hot air



Hand extruder welding machine



Automatic machine by hot wedge



Installation clamps



Cutter



Contact Thermometer

Geometric shapes / Types



Automatic welding with hot air or wedge



Cleaning of the welding area



Radial smoothing



"T" cross extrusion



Extrusion patch

www.atarfil.com



Ctra. Córdoba, Km. 429 - Complejo El Rey
E-18230 Atarfe (Granada) SPAIN
Central Tel.: +34 958 439 200
Fax: +34 958 43 91 28




Member of



Welding Quality Control



Field Tensiometer



Sample Cutter




Shear Test



Spark or potentiometer Test



Peeling Test



Air pressure Test



Resistance Test



Vacuum Test

Execution at the Job Site




Panel cutting and transport :
Platform minimum 3,5 m width



Distribution of cut panels
at the crest of the slope



Excavation of anchorage ditch



Panel extensión, welding
and provisional ballasting with bags



Panel extension and welding at the bottom.
Distribution of final ballasting with concrete kerbs




Ballasting with intermediate berm



Final transversal ballasting
with upper anchorage by ballast weight



Pipe welding



Juncture with profiles



I/O juncture with pipe



Water entry



Spillway



Ramp